E 0315Z 25 JAN 61	SECRET	2 3	5 6
*DIRECTOR			
70N: OPS (1-2-3-4)		RO	UTINE
DL TOR 0336Z 25 JAN 61			IN 43858
		CI	78033 4 25X1A

SLIPPER TANK FUEL PROBLEM ARTICLE 351. SUGGEST REMOVE RAM AIR TUBES, AUX TANK AND ENERGIZE A50126-1 SHUT OFF VALVE IF NOT ALREADY ACCOMPLISHED.

END OF MESSAGE

Jhm